









PBI power connector

Цепь	Конт.
1	+36
2	+7.5
3	+22
4	+12V
5	GND
6	+5V
7	+15V
8	+3.3V

Openbox power connector

Цепь	Конт.
1	+22
2	GND
3	+12V
4	+6.5
5	GND
6	+5V
7	GND
8	+3.3V

PBI power 3
 Flymouse
 @yandex.ru